



Test Report

Number: SZHH01060058

Applicant: SHENZHEN KIMYE ACETATE MANUFACTORY
9# DAWANG INDUSTRIAL ZONE, DAKANG
XINTANG VILLAGE, HENG GANG LONG GANG,
SHENZHEN, CHINA

Date: May 27, 2016

Attn: ZHENG YU WU

Sample Description:

One (1) submitted sample said to be **cellulose acetate**.


Reference No. : K1092/6.0MM.

Manufacturer : Shenzhen KIMYE Acetate Manufactory.

Country of Destination : America.

Country of Origin : China.

Date Sample Received : May 21, 2016.



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

Conclusion:

Tested Samples

Tested components of
submitted samples

Test Item

Bisphenol-A content

Result

See test conducted

Authorized by:
For Intertek Testing Services
Shenzhen Ltd.

Ben N.L. Lin
General Manager



Page 1 of 2

Intertek Testing Services Shenzhen Ltd.- Hardlines

深圳天祥质量技术服务有限公司-轻工产品事业部

301A, 302B, 6/F. 7/F Shekou Technology Main Bldg. and Room 1E of Nanshan Building,

Nanhai Ave., Nanshan District, Shenzhen, China

深圳市南山区南海大道科技大厦 301A、302B、六层、七层、南山大厦 1 楼 1E 房

Tel: (86-755) 2602 0111 Fax: (86-755) 2683 7118/9 Postcode: 518067

www.intertek.com www.intertek.com.cn China Toll-Free: 400 886 9926

Attention is drawn to the terms and conditions printed overleaf.

**Test Report**

Number: SZHH01060058

Tests Conducted

1 Bisphenol-A Content

Solvent extraction method was used and Bisphenol-A content was determined by High Performance Liquid Chromatographic (HPLC).

Element	Result (ppm)	Reporting limit (ppm)
	Tested component	
	(1)	
Bisphenol-A	ND	1

ppm = parts per million = mg/kg

ND = Not Detected

Tested Component: (1) Pink plastic.

End of report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.



Page 2 of 2

Intertek Testing Services Shenzhen Ltd.- Hardlines

深圳天祥质量技术服务有限公司-轻工产品事业部

301A, 302B, 6/F. 7/F Shekou Technology Main Bldg. and Room 1E of Nanshan Building,

Nanhai Ave., Nanshan District, Shenzhen, China

深圳市南山区南海大道科技大厦 301A、302B、六层、七层、南山大厦 1 楼 1E 房

Tel: (86-755) 2602 0111 Fax: (86-755) 2683 7118/9 Postcode: 518067

www.intertek.com www.intertek.com.cn China Toll-Free: 400 886 9926

Attention is drawn to the terms and conditions printed overleaf.